

Factura

Furnizor: S.C. AUTO COBALCESCU S.R.L.

Factura Nr.: SP3315704

Nr. Aviz ins. marfa:

Data Fact.: 27.09.2022

CLIENT: Societate ADMINISTRARE ACTIVE SECTOR
3 SRL

Nr.Reg.Comert: J40/14752/2012

CUI/CNP: RO31012790

Sediul: CAL. VITAN, NR.242, ET.P, CAM.6, SCT.3

Romania SECTOR 3

3 Conditii de plata: OP

Data Scadenta: 17.10.2022

Asigurator:

S.C. ADMINISTRARE ACTIVE SECTOR 3 S.R.L.

STI Nr.: INTRARE 20356
IESIRE
Zi 27 Luna 09 An 2022

Nr. O.R.: 310108875

Cota TVA: 19 %

Pag	Serie sasiu	Data reparatiei		Kilometraj	Nr inmatriculare		Tip APV	Data livrare
1	UU1L5220X61880813	27.09.2022		40197	B310AAS		L8N	27.09.2022
Denumire produs sau servicii	Cod Reper	U.M.	Cant/ Timp	Red %	Pret Unit net	Valoare unit (fara TVA)	Valoare total (fara TVA)	Valoare TVA
1	2	3	4	5	6	7	8	9
REVIZIE ANDURANTA BENZINA RN 0700 / 10W40 Kit curea accesorii			1,00 1,00					

Mașina
OG REVIZIE VEHICUL
OS DEM-REM FILTRU DE AER
OS INLOC FILTRU HABITACLU
OG INLOC CUREA DE ACCESORII
INLOCUIRE BEC x 2
OG INLOCX2 DISC DE FRANA FATA
OS DIAGNOST CIRCUIT DE FRANARE

Piese
GARNITURA BUSON ULEI
FILTRU AER
FILTRU POLEN
DISC FRANA FATA
SET PLACUTE FRANA
ULEI DACIA PLUS EXTRA 10W40 1L
DACIA OIL PLUS EXTRA 10W40 4L
BEC 12 V - 5 W
FILTRU ULEI
*COLECTIE ACCESORII
COLECTIE CUREA ACCESORII
SPRAY

TOTAL (fara TVA) Piese de schimb

Numar ore facturate: 3,70 ore

Semnatura si stampila furnizorului	Date privind expeditia Numele delegatului Buletinul/carte de identitate Seria: Nr. CNP: Mijlocul de transport Nr. Inmat.: Expedierea s-a facut in prezenta noastra La data de 27.09.2022 Acu 15:18	Semnatura de primire Semnatura clientului pe avizul de insotire a marfii certifica primirea facturii	TOTAL (fara TVA) TVA TOTAL de plata 1.825,13
------------------------------------	--	--	--

Telefoane utile: Mec. Renault: 03741 02336/7; Mec. Dacia: 0374 102342/3; Mec. Nissan: 0374 102364; Mec. SAAB: 021 5297222; Caroserie: 0374 102347/8

Comentariu auto: