

Factura

Furnizor: S.C. AUTO GOBALCESCU S.R.L.	Factura Nr. : SP3334942 Nr. Aviz ins. marfa : Data Fact.: 31.08.2023	CLIENT: Societate ADMINISTRARE ACTIVE SECTOR 3 SRL Nr.Reg.Comert: J40/14752/2012 CUI/CNP: RO31012790 Sediul: CAL. VITAN NR.242 ET.P CAM.6 BUC Romania SECTOR 3
Conditii de plata: OP Data Scadenta: 20.09.2023 Asigurator:		
Nr. O.R. : 310117997		

Cota TVA: 19 %

Pag	Serie sasiu	Data reparatiei	Kilometraj		Nr inmatriculare	Tip APV	Data livrare		
1	VF1HJD40461724289	22.08.2023	131025		B304AAS	HMM	22.08.2023		
Denumire produs sau servicii	Cod Reper	U.M.	Cant/ Timp	Red %	Pret Unit net	Valoare unit (fara TVA)	Valoare total (fara TVA)	Valoare TVA	
1	2	3	4	5	6	7	8	9	
Manopera OG INLOC SONDA DE OXIGEN AVAL OS CTR FUNT CALCULATORARE									
Piese SONDA OXIGEN									

Numar ore facturate: 2,00 ore

Semnatura si stampila furnizorului	Date privind expeditia Numele delegatului	Semnatura de primire	TOTAL (fara TVA) TVA
Date privind intocmirea facturii Nume si prenume responsabil Smochina Radu	Seria: Nr. CNP. : Mijlocul de transport: Nr. Inmat.:	pe avizul de insotire a marfii certifica primirea facturii	TOTAL de plata 1.100,02
CNP:	Expedierea s-a facut in prezenta noastra La data de 31.08.2023 Acu 9:47		

Telefon : +40 374 495 486

Comentariu auto:

S.C. ADMINISTRARE ACTIVE SECTOR 3 S.R.L.

Nr.: INTRARE 18556

IESIRE

Zi. 31 Luna 08 An 2023